

**Danicorp, Inc.**  
**14467 Meridian Pkwy #B**  
**Riverside, CA 92518**  
**(951) 653-0007 Fax: (951) 653-0082**  
**E-mail: danicorp@msn.com**

June 5, 2019

Amron International  
1380 Aspen Way  
Vista, CA 92081

To Whom It May Concern:

This letter is a written confirmation that Danicorp, Inc. (hose assembly manufacturer) received the first ContiTech/Goodyear Low Pressure (LP) hose shipment at our factory on February 22, 2018. This product is now suspected of not adhering to the ANSI Z86 7.1 standard.

The ContiTech/Goodyear hose may have been used on some/all LP assemblies beginning after February 22 through September 30, 2018. Hose material marked with the Julian date codes of: 0308, 0388, 0598, 0808, 1648, 1738, and 1998 are the only hoses in question. These hose assemblies will have Danicorp's date coding (on the ferrule), as early as, D0218 (February 2018) through D0918 (September 2018). We were notified on September 15th to suspend use of all ContiTech/Goodyear LP hose with the above hose Julian date codes.

On October 1, 2018, Danicorp Inc. revisited its crimping procedures to ensure the quality of the hose assembly, and only used saved stock of Gates LP hose to produce any/all LP hose assemblies for Amron Intl.

Please see the attached list of hoses that were sold to Amron International during the timeframe the suspect ContiTech/Goodyear product was used.

Best regards,

Kim Martin  
General Manager